



**Figure 23. Mainshaft and Fractured Torsion Shaft Piece**